

Interior - Driver's Seat Won't Move Forward/Backward

[Notes](#)

Classification:
EL02-023

Reference:
ITB00-067a

Date:
June 4, 2002


2000-2001 I30 AND 2002 I35; DRIVER'S SEAT WILL NOT MOVE FORWARD OR BACKWARD

This bulletin amends ITB00-067. This version includes additional Model and Model Year application. Please discard all paper copies of the earlier bulletin.

APPLIED VEHICLE(S):
2000-2001 I30 (CA33)
2002 I35 (CA33)

SERVICE INFORMATION





Zoom

Sized for Print

If the driver's seat in an applied vehicle will not move in the forward or backward direction, the seat slide motor and gear assembly may need replacement (see figure 1).

If this should occur, follow the Service Procedure in this bulletin to assist in diagnosing the incident and, if necessary, install the Seat Slide Motor kit (see the Parts Information section of this bulletin).

NOTE: This is the ONLY approved repair procedure for this incident. A claim to Infiniti division for the repair of this incident may be denied if the repair is not performed exactly as outlined in this bulletin.

| DESCRIPTION | PART # | QUANTITY |
|----------------------|-------------|----------|
| Seat Slide Motor Kit | 87562-C9926 | 1 |

Zoom

Sized for Print

PARTS INFORMATION

CLAIMS INFORMATION

NOTE: This is the ONLY approved repair procedure for this incident. A claim to Infiniti division for the repair of this incident may be denied if the repair is not performed exactly as outlined in this bulletin.

| DESCRIPTION | PFP | OP CODE | SYM | DIA | FRT |
|-----------------------------|-------------|---------|-----|-----|-----|
| RPL Slide motor & gear assy | 87562-C9926 | VH80AA | ZE | 32 | (1) |

1. Please reference the current Infiniti Warranty Flat Rate Manual and use the indicated FRT.

Zoom

Sized for Print

Submit a Primary Failed part (PP) line claim using the claims coding table as shown.